

The Port Connector as it is shipped (all connected together)

The port connector taken apart, the parts layed out ready to be installed.





The connector installed (loosely) on the block.
Please note the location of the copper washers.

Do not overtighten.